







## 2.1 MAIN SCREEN

---




	Switch language Chinese/English
	Switch to "Manual Mode" screen
	Switch to "Auto Mode" screen
	Switch to "Setting" screen
	Switch to "System Info" screen








## 2.2 MANUAL MODE




<p>Degree</p>	<p>Turn table current position: Blue field: current position. Red field: set position.</p>	<p>Go to</p>	<p>Move to set position</p>
<p>Rpm</p>	<p>Turn table rotation per round (RPM) setting</p>	<p>Go to 0</p>	<p>Return to beginning position</p>
<p>Reset</p>	<p>Reset current position to 0</p>	<p>Lock</p> <p>Weld</p>	<p>Manual activate welder. First unlock the function by pressing the “Lock” button and press “Weld” button to activate welder.</p>
<p>H / L</p>	<p>Toggle between welding/high turn table speed.</p>	<p>Output-1</p>	<p>Force output-1 ON/OFF.</p>
<p>Continue</p>	<p>Jog operation mode. 1. Hold/release the button to rotate. 2. Press to toggle rotation ON/OFF.</p>	<p>Output-2</p>	<p>Force Emulator ON/OFF.</p>
<p>Turn table</p>	<p>Turn table jog operation.</p>	<p>Output-3</p>	<p>Force dry contact output ON/OFF.</p>
<p>Up</p> <p>Down</p>	<p>Turn table tilting operation.</p>		<p>Switch to welding sequence screen.</p>









## 2.3 AUTO MODE




<p>Degree</p> <p>180.0</p> <p>170.0</p>	<p>Turn table current position: Blue field: current position. Red field: set position.</p>	<p>mm</p> <p>314</p> <p>314</p>	<p>Turn table current position according to angle &amp; diameter: Blue field: current position. Red field: set position.</p>
<p>Rpm</p> <p>1.000</p>	<p>Turn table rotation per round (RPM) setting.</p>	<p>mm/min</p> <p>628</p>	<p>Turn table linear speed (mm/min) setting.</p>
<p>Reset</p> 	<p>Reset current position to 0</p>	<p>Diameter</p> <p>200</p>	<p>Welding diameter.</p>
<p>H / L</p> 	<p>Toggle between welding/high turn table speed.</p>	<p>Ampere A2 (%)</p> <p>50.0</p>	<p>Welding current %. 0~100% = 0~15VDC If pulse mode is active, represents the peak %. (please refer to sec 2.8)</p>
<p>Continue</p> 	<p>Jog operation mode. 3. Hold/release the button to rotate. Press to toggle rotation ON/OFF.</p>	<p>Voltage CH2 (%)</p> <p>50.0</p>	<p>Second analog voltage output. 0~100% = 0~15VDC</p>
<p>Turn table</p> 	<p>Turn table jog operation.</p>	<p>Weld</p> 	<p>Simulation/Auto mode toggle. Welder ON is disable when Simulation mode is active.</p>
	<p>Switch to welding sequence screen.</p>		<p>Activate/stop auto welding sequence.</p>





## 2.4 SETTING



<p>Program</p> 	Switch to Program screen.
<p>Note</p> 	Switch to Program note screen.
<p>Sequence</p> 	Switch to Weld Sequence screen.
<p>Current</p> 	Switch to Weld Current screen.
<p>Index weld</p> 	Switch to Index Weld screen.
<p>Function</p> 	Switch to Autorun function screen.
<p>System</p> 	Switch to system setting screen. User level 1 clearance is required. Default user level 1 clearance password: 123 Default user level 2 clearance password: 456
<p>Backup</p> 	Switch to Program Backup screen.

## 2.5 PROGRAM SAVE/LOAD

16:11:21		PROGRAM		05/25/2016	
00	TEST	NO.	Program name		
<input type="button" value="Load"/> ←		00	TEST	→ <input type="button" value="Save"/>	
00	TEST	05		<input type="button" value="▲"/> <input type="button" value="▼"/>	
01		06			
02		07			
03		08			
04		09			
<input type="button" value="Home"/>		<input type="button" value="MANU"/>		<input type="button" value="AUTO"/>	
		<input type="button" value="SET"/>			

	<p>Enter the program number in No. field and press "Load" button to load the program's welding parameter.</p>
	<p>Enter the program number and program name, the press "Save" to save the parameters.</p>
	<p>Press ▲ or ▼ button to scroll to next/previous sets of parameters</p>
	<p>Switch to Program note screen.</p>

## 2.6 PROGRAM NOTE


---

Enter letter or number as program reminder. 10 letters for short field, 24 letters for long field

00	TEST	NOTE
1234567890		
ABCDEFGHIJ		


 **MANU** **AUTO** **SET** 

## 2.7 WELDING SEQUENCE SETTING



T1	Emulator ON delay after auto start is activated.
T2	Welder ON delay after Emulator is activated.
T3	Turn table rotation delay after arc on signal is received.
T4	Dry contact output ON delay after auto start is activated.
T5	Welder OFF delay after turn table has reached target program position.
T6	Turn table stop delay after welder is OFF.
T7	Torch up delay after turn table is stopped.
T8	Emulator off delay after torch is raised.
T9	Dry contact output OFF delay after turn table has reached target program position.

## 2.8 WELDING CURRENT SETTING



A1	Initial current (%)	0~100%, Initial current level after arc ON signal is received.
A2	Peak current (%)	10~100%, main welding current. If pulse wave function is enabled, this value is the peak current value.
A3	Valley(low) current(%)	0~100%, If pulse wave function is enabled, this value is the low current value. Can't set more than A2
A4	Welding crater current(%)	0~100%
T1	Initial current time(sec)	0~10 sec, initial arc stabilize time after arc ON signal is received.
T2	Rise current time(sec)	0~10 sec, rise time from initial current A1 to peak current A2
T3	Peak current time(sec)	0.01~10 sec, peak current duration before change to valley current.
T4	Valley current time(sec)	0.01~10 sec, valley current duration before change to peak current.
T5	Current fall time(sec)	0~10 sec, amount of time current drop from A2 to A4. The count starts after welder output is switched off.
T6	Welding crater time(sec)	0~10 sec, amount of time for crater current
CH2	Analog voltage(%)	Channel 2 analog voltage 0~100% = 0~15VDC

Note 1: If both T3 & T4 are set to 0, the wave pulse function is disabled.

**Caution: Even though pulse wave function's output voltage can reach a frequency of 50Hz, the welder may not be able to change current at this rate.**

## 2.9 INDEX WELD SETTING

16:32:50
Index Weld
05/25/2016

n (repeat)

2

a ~ b (Weld)

170.0

Rpm(a~b)

1.000

b ~ c (Move)

10.0

Degree

0180.0

Rpm(b~c)

2.000

Go to "b"

↻

⏏

↻

↺

🏠

MANU


AUTO



SET

⏏

<p style="text-align: center;">n (repeat)</p> <div style="border: 1px solid red; padding: 2px; display: inline-block; color: red; font-weight: bold; font-size: 1.2em;">2</div>	Set number of index welding
<p>Rpm(a~b)    a ~ b (Weld)</p> <div style="display: flex; justify-content: space-around;"> <div style="border: 1px solid red; padding: 2px; display: inline-block; color: red; font-weight: bold; font-size: 1.2em;">1.000</div> <div style="border: 1px solid red; padding: 2px; display: inline-block; color: red; font-weight: bold; font-size: 1.2em;">170.0</div> </div>	a ~ b : Set index welding angle and speed.
<p>Rpm(b~c)    b ~ c (Move)</p> <div style="display: flex; justify-content: space-around;"> <div style="border: 1px solid red; padding: 2px; display: inline-block; color: red; font-weight: bold; font-size: 1.2em;">2.000</div> <div style="border: 1px solid red; padding: 2px; display: inline-block; color: red; font-weight: bold; font-size: 1.2em;">10.0</div> </div>	b ~ c : Set positioning angle and speed.
<div style="display: flex; gap: 5px;"> <div style="border: 1px solid gray; padding: 2px; color: red; font-size: 1.2em;">⏏</div> <div style="border: 1px solid gray; padding: 2px; color: red; font-size: 1.2em;">↻</div> <div style="border: 1px solid gray; padding: 2px; color: red; font-size: 1.2em;">↺</div> </div>	Turn table jog operation.
<p style="text-align: center;">Go to "b"</p> <div style="border: 1px solid red; padding: 2px; display: inline-block; color: red; font-size: 1.5em; text-align: center;">↻</div>	Move to position "b"

## 2.10 AUTORUN FUNCTION



 	X : Disable feature O : Enable feature
"Arc ON" feedback	X : Turn table doesn't wait Arc on feedback signal. Turn table start rotation T3 sec after welder on signal is active O : Turn table waits for Arc on feedback signal. Turn table start rotation T3 sec after receiving arc on feedback.
PT : Start = 0	Reset current position to 0 when auto start is activated.
After welding stop, return to the starting point.	Automatically return turn table to original position.
Foot switch	Foot switch function: Rotate CW, rotate CCW, Auto Start.
Emulator : Enable	Activate/disable emulator. When emulator sensor is disabled, emulator sensor is also disabled.
Torch : sensor	Torch sensor enabled. System checks whether torch is raised/lowered before activating emulator (see Sec.2.7)
Emulator : sensor	Emulator sensor enabled. System checks whether emulator is ON/OFF before activating welder(see Sec.2.7)